iccen †

k

THE OFFICE OF BRIDGE MAINTENANCE

NATIONAL BRIDGE INVENTORY STRUCTURE INVENTORY AND APPRAISAL REPORT

IDENTIFICATION (1)State Name- SOUTH CAROLINA Code 454	
(8)Structure Number # 0004670081600200 Asset ID 2441	Sufficiency Rating = 37.0 Functionally Obsolete = YES
(5)Inventory Route (On/Under) On - 171008160	Structurally Deficient = YES
(2)State Highway Department District 4	
(3)County Code 91 (4) Place Code	CLASSIFICATION Code
(6)Features Intersected MUD CREEK	(112) NBIS Bridge Length - YES
(7)Facility Carried S-46-816	(104) Highway System - NOT NHS 0
(9)Location 3.2 MI W HICKORY GROVE	(26) Functional System - RURAL-LOCAL 9
(11)Milepoint 2.973	(100) Strahnet Highway - NOT STRAH HWY 0
(12)Base Highway Network - NOT PART OF NET Code 0	(101) Parallel Structure - NONE EXIST N
(13)LRS Inventory Route & Subroute	(102) Direction of Traffic -2-WAY TRAFFIC 2
(16)Latitude 34 Degrees 59 Minutes 11.34 Seconds	(103)Temporary Structure -
(17)Longitude 81 Degrees 28 Minutes 18.15 Seconds	(105)Federal Lands Highways - N/A 0
(98)Border Bridge State Code % SHARE %	(110) Designated National Network - NO 0
(99)Border Bridge Structure No. #	(20)Toll - ON FREE ROAD 3
STRUCTURE TYPE AND MATERIAL	(21) Maintain - SCDOT
(43)Structure Type Main: MATERIAL - PRESTRESSED CON	(22)Owner - SCDOT
Type - STRINGER/MULTI-BEAM OR GIRD Code 502	(37) Historical Significance - NOT DETERMINABLE 4
(44)Structure Type Main: MATERIAL - OTHER OR N/A	
Type -OTHER OR N/ACode000	CONDITION Code
(45)Number of Spans in Main Unit 3	(58) Deck - FAIR 5
(46)Number of Approach Spans 0	(59)Superstructure - FAIR 5
(107) Deck Structure Type - CONCRETE CAST-IN-PLC Code 1	(60)Substructure - POOR 4
(108)Wearing Surface / Protective System:	(61) Channel and Channel Protection - BNK PRT REPAIR 7
A)Type of Wearing Surface - BITUMINOUS Code 6	(62) Culverts - NOT APPLICABLE N
B)Type of Membrane - UNKNOWN Code 8	LOAD RATING AND POSTING Code -
C)Type of Deck Protection - UNKNOWN Code 8	(31) Design Load -H 15 2
AGE AND SERVICE	(64) Operating Rating - LF 62
(27)Year Built 1956	(66) Inventory Rating - LF 23
(106)Year Reconstructed 0	(70) Bridge Posting - EQUAL/ABOVE LEGAL LOADS 5
(42)Type of Service On - HIGHWAY	
Under -WATERWAY Code 5	(41) Structure Open, Posted or Closed - A
(28)Lanes: On Structure = 2 Under Structure = 0	Description - OPEN, NO RESTRICT
(29) Average Daily Traffic 0 (20) Verage ADT 0047 (20) Truck ADT 00 0	APPRAISAL Code -
(30)Year of ADT 2017 (109)Truck ADT 00 %	
(19)Bypass, Detour Length 0 MI	(67) Structure Evaluation- INTOLERABLE; HIGH PRI3(68) Deck Geometry6
GEOMETRIC DATA	(69) Underclearances, Vertical and Horizontal N
(48)Length of Maximum Span 30 FT	(71) Waterway Adequacy 7
(49)Structure Length 90 FT	(72) Approach Roadway Alignment 8
(50)Curb or Sidewalk: Left .7 FT Right .7 FT	(36) Traffic Safety Features 0000
(51)Bridge Roadway Width Curb to Curb 24.3 FT	(113) Scour Critical Bridges - SCOUR CRIT, UNSTABLE 3
(52)Deck Width Out to Out 25.6 FT	
(32) Approach Roadway Width (W/Shoulders) 33 FT	PROPOSED IMPROVEMENTS
(33)Bridge Median - NONE Code 0	(75) Type of Work - REPLACE/LOAD CAPACITY Code 311
(34)Skew 0 Deg (35) Struture Flared NO	(76) Length of Structure Improvement 117.0 FT
(10)Inventory Route Min Vert Clear 99 FT 99 IN	(94) Bridge Improvement Cost \$284,000.00
(47)Inventory Route Total Horz Clear 24.3 FT	(95) Roadway Improvement Costs \$71,000.00
(53)Min Vert Clear Over Bridge Roadway 99 FT 99 IN	(96) Total Project Cost \$426,000.00
(54)Min Vert Underclear Ref - NOT HWY OR RXR 0FT 0 IN	(97) Year of Improvement Cost Estimate 2019
(55)Min Lat Underclear Right Ref-NOT HWY OR RXR 99.9FT	(114) Future AADT 68
(56)Min Lat Underclear Left .0FT	(115) Year of Future AADT 2037
(38)Navigation Control - NONE Code 0	(90) Inspection Date 01/2019 (91) Frequency 24 Mo
(111)Pier Protection - Code	(92) Critical Feature Inspection: (93) CFI Date
(39)Navigation Vertical Clearance FT	A) Fracture Crit Detail NO Mo A)
(116)Vert-Lift Bridge Min Vert Clear FT	B) Underwater Insp NO Mo B)
(40)Navigation Horizontal Clearance FT	C) Other Special Insp YES Mo 24 C) 5/1/2019
(+v)Navigation nonzontal clearance FI	